





Milepost 136, 103 Kisco Avenue (C001)

Legend

-  - Radon Sample Location
-  - Exterior Wall
-  - Interior Wall
-  - Entry door



Weston Solutions, Inc.

In Association with Scientific and Environmental Associates, Inc.,
Environmental Consultants, Inc., Avatar Environmental, LLC,
On-Site Environmental, Inc. and Sovereign Consulting, Inc.

Figure 6A: C001 Radon Analytical Results Map

Canadian Radium and Uranium Site
Mount. Kisco, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

Notes:

Radon sampling was conducted using charcoal canisters
Radon analytical results are reported in pico curies per liter (pCi/L)

EPA OSC:

E. DALY

RST SPM:

B. NWOSU

PROJECT #:

30400.021.006.2053